

Report ID: 26,504,527 Version: 1 10 Jan 2025 Created:

Make:	Peugeot	Model:	308	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	Registration:	HGS910	Reg Expiry:	10 Feb 2025	Engine	1		1
WoF Expiry:	22 Jan 2026	Odometer:	74,431 Kms	Good No:	26504527	Oil level	~		
VIN:	VF34C5FVADS115715	Next Service:	80000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	SC					Performance	~		
Key:		-0	LSC	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			TIN		Operation	~		
R = rust PT = paint def				\int		Noise	~		
C = crack					SC	Clutch			~
P = pin dent						CV joints	~		
* = decals	ssc 916			- AL	ELIP S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC P						Performance	~		
		Note: son	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Ins	pection Comments	Note: Joh		indy not be disp	ayea in the diagram		•	oftyre))
						Left front	s (lowest observed tread depth of tyres) t front 3.5		
									mm
						Right front Left rear		.5	mm
								.5	mm
Conditions During Body Inspection: Dry						Right rear			mm
Under Carriage & Under Bonnet Inspection Comments							Spare Yes		
		meenspeede	<u>on comments</u>			Suspension			1
Battery pas	sed test					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
Interior Comments						Operation	~		
						Electrical / Accessories	1		
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
curpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Case					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
A/c working	g at time of inspection. I	No reverse came	ra or nav. 95 octane pe	etrol fuel		Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
	LL Devile 11					- 001 001	25		•
Inspected by: Reuben Harvey						Date: 03 Jan 202	25		
I have read	and understood th	is condition c	juide. Name: .			Signature:			