

Report ID: 26,504,687 2 Version: 30 Dec 2024 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2016	<b>Registration:</b>	PMQ549	Reg Expiry:	01 Mar 2025	Engine	1		L
WoF Expiry:	03 Jan 2026	Odometer:	124,426 Kms	Good No:	26504687	Oil level	~		
VIN:	7AT0GF09X22012638	Next Service:	due	Service Histor	<b>y:</b> No	Smoke & fumes	r		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged f	or an additional d	inarge.	Coolant condition	~		
	SC		SC SC		SC	Performance	~		
Key:				5(0)-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
R = rust	SC DIA			710	S SC	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	sc dle				2414	CV joints	~		
* = decals		10		10	E SC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W – significan	S SC		S SC S SC		S	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishe	es may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Fr foot panel minor dent						Left front	ont 5 m		
						Right front	5	5	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Wet						Right rear	5 mm		
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
All wheel di	rive/					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
	Avelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Average					Wipers (front & rear)	~		
	rd Average					Window winder FL	~		<u> </u>
Concert						Window winder FR	~		<u> </u>
General Comments					Window winder RL	~		<u> </u>	
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Remote locking	~		<u> </u>
						Sat. Nav. (basic test only)			~
Evidence	or Carri Beit Replac	ement: N	10	Kms:		Reversing camera	~		
Inspected	d by: Uriah Pepene					Date: 30 Dec 20	24		
. · · ·									

I have read and understood this condition guide.

Name: .....

Signature: .....