

Report ID: 26,504,768 1 Version: 20 Dec 2024 Created:

Make:	BMW	Model:	1 Series	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	Registration:	PLF931	Reg Expiry:	31 Jul 2024	Engine			
WoF Expiry:	18 Dec 2025	Odometer:	53,843 Kms	Good No:	26504768	Oil level	~		
VIN:	WBA1A12040J204473	Next Service:	55000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	r an additional c	narge.	Coolant condition	~		
			Р			Performance	~		
Key:		=		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints			~
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	3 mm		
						Right front	3 mm		mm
						Left rear	4	1	mm
Conditions During Body Inspection:						Right rear	4 mm		
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Lukin Koveskali Date: 20 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: