

Basic Vehicle Condition Guide

Report ID: 26,505,519


Version:

Created: 07 Jan 2025

Make: Model: Toyota Prius **Body Style:** Hatchback Year: 2011 Registration: JCL902 Reg Expiry: 08 Jul 2025 **WoF Expiry: Odometer: Good No:** 18 Nov 2025 151,012 Kms 26505519 VIN: 7AT0H637X15065170 Next Service: 160500km Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Vehicle drove well

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Aaron Johnson Date: 07 Jan 2025

Name:

Pass	Fail	N/A
	1 all	IN//
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
-		
~		
~		
l depth	of tyre	<u> </u> 25)
		mm
		mm
3 1 1 1		mm
		mm
	110	
<i>V</i>		
ν ν		
<i>V V</i>		
<i>V V V</i>		
<i>V V</i>		
<i>V V V</i>		
V V V		
VVV		
VVV		
VVV		
\(\times \) \(\t		
V V V V V		
V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V		
V V V V V V V V V V V V V V V V V V V		
ン ン ン ン ン ン ン ン ン ン ン ン ン ン		
V V V V V V V V V V V V V V V V V V V		
ン ン ン ン ン ン ン ン ン ン ン ン ン ン		
	3.	イ

Signature: