

Report ID: 26,505,601 1 Version: 23 Dec 2024 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2008	<b>Registration:</b>	QRA412	<b>Reg Expiry:</b>	18 Jan 2025	Engine			•	
WoF Expiry:	26 Dec 2025	Odometer:	130,760 Kms	Good No:	26505601	Oil level	~			
VIN:	7AT0CJ3MX22201078	Next Service:	137,000kms	Service Histor	<b>y:</b> No	Smoke & fumes	V			
						Performance	r			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	V			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
	P SC W		S SC S SC	S	S	Performance	V			
Key:	Lt 3C W	-0	330 330			Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent R = rust						Operation	~			
PT = paint defect						Noise	~			
C = crack						Clutch			~	
P = pin dent						CV joints	~			
* = decals SC 919 PT SC						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S SC S SC W S W W						Performance	~			
Redulmenter Commenter Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread	•	oftvre	<u>ا</u> مح	
Left wing mirror indicator lens cracked.									mm	
						Right front		3	mm	
						Left rear		3	mm	
Conditions During Rody Inspection:						Right rear				
Conditions During Body Inspection: Dry						Right rear 4 mm   Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
		p				Suspension performance	~		I	
						Steering performance	~			
Shock absorb							~	~		
							V			
						Air Conditioning / Heater				
Interior Comments						Operation				
						Electrical / Accessories				
Seats	Splits on o	drivers seat.				Head lights	~			
Carpets	Average					Tail lights	•			
						Indicators	~			
Panels	Door arm	s scratched, cargo	o blind missing.			Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	~			
						Window winder FL	~			
General Comments						Window winder FR	~			
						Window winder RL	~			
Noise in pulley / belt area. Steering feels a bit heavy.						Window winder RR	~			
	tis a Dit Heavy.					Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
Engine Timing Mechanism: Comhelt						Remote locking	~			
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~	
Evidence	or Cam Belt Replac	ement: N	10	Kms:		Reversing camera	~			
Inspected by: Daryll Timms						Date: 23 Dec 2024				

I have read and understood this condition guide.

Name: .....

Signature: .....