

Report ID: 26,505,638 Version: 1 23 Dec 2024 Created:

Make:	BMW	Model:	116	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2005	Registration:	JRG603	Reg Expiry:	02 Sep 2025	Engine			1	
WoF Expiry:		Odometer:	115,413 Kms	Good No:	26505638	Oil level	~		<u> </u>	
VIN:	WBAUF12050PN26874	Next Service:		Service Histor		Smoke & fumes	~			
			120,300			Performance	~			
Note: This report is not a warranty						Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition				
						Performance	~		──	
Key:	SDPSCWS	w b	S SC W S SC W		S SC W	Radiator / Hoses (visual)	~		+	
S = scratch						Transmission	V			
D = dent SSCW									T	
R = rust				10		Operation Noise	~		──	
PT = paint def C = crack	ect M			+	PT SC	Clutch	~		<u> </u>	
C = Crack P = pin dent	LHE	KI		-					~	
* = decals	SSCW PR				ELER SW	CV joints	~		──	
SC = stone chips						Wheel bearings	~			
W = significant scuffs SC S W S D P W S D W S W S SC W						Brakes				
						Performance	~		──	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		6 .	Ļ	
Accident damage to LH/F door,						Tyres (lowest observed tread depth of tyres)				
						Left front	6 mm			
						Right front		5	mm	
						Left rear		3 mm		
Conditions During Body Inspection: Wet						Right rear	3 mm			
						Spare No				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Rear wheel	drive, Engine sump lea	king, Rear main l	eaking			Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Commonte						Operation		~		
Interior Comments						Electrical / Accessories				
Seats	Poor					Head lights	~			
Carpets	A					Tail lights	~			
Carpets	Average					Indicators	~			
Panels	Average					Dashboard warning lights	~			
Dealth						Wipers (front & rear)		~		
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u>					Window winder RL	~				
Drivers seat base & back torn, Seats stained, Radio screen not working, Front interior light coming out of roof,					-	Window winder RR	~			
Roof lining	coming down, Gear lev	er chrome peelir	ng & sharp, Air-con not	working, Wipers	need replacing,	Rear view mirrors	~			
						Radio (basic test only)		~		
						CD (basic test only)		~		
						Number of keys	1			
Road Conditions During Test Drive: Wet						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
	d by: Andre Richards					L	24			
Inspecte	Date: 23 Dec 20	24								
I have read	and understood th	is condition o	uide. Name: .			Signature:				