

Report ID: 26,505,896 1 Version: 09 Jan 2025 Created:

Make:	Holden	Model:	Cruze	Body Style:	Sedan		Pass	Fail	N/A
Year:	2010	Registration:	FJN809	Reg Expiry:	12 May 2025	Engine	1		1
WoF Expiry:	19 Aug 2025	Odometer:	200,955 Kms	Good No:	26505896	Oil level		~	
VIN:	KL3JA695JAK677033	Next Service:	204,000	Service History	/: Yes	Smoke & fumes	r		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition		~	
			D			Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			1
D = dent	s c s c w			The	S SC	Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	HIG				741L	CV joints	~		•
* = decals	SDSC 91		<u> </u>	The	ELL SD	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs						Performance		~	
Rody Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~	-	
Body Inspection Comments						Tyres (lowest observed tread depth o		oftvre	 >s)
						Left front		.0	mm
						Right front			mm
						Left rear			mm
						Right rear	5.0		mm
Conditions During Body Inspection: Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
onder earlage a onder bonneernspeellon comments						· · · · · · · · · · · · · · · · · · ·			
Coolant co	ndition poor and has sig	gns of additive ar	nd oil. Brake fluid low. (Dil leak		Suspension performance		~	
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation Electrical / Accessories	~		
Seats	marks, dri	vers has hole				Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	scratches	scuffs marks driv	ers arm rest broken			Dashboard warning lights		~	
Dashboa	ord scratches					Wipers (front & rear)	~		
						Window winder FL	~		
General	Comments]	Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Steering wheel off centre. Air conditioning not very cold. Rhs air vent broken. Engine light came on during						Window winder RR	~		
road test						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
		<u> </u>				Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			<
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Gary Adams						Date: 31 Dec 2024			
Inspected by. Outprivations Date: 51 Dec 2024									
I have read and understood this condition guide. Name:									