

Report ID: 26,506,721 2 Version: 07 Jan 2025 Created:

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	<b>Registration:</b>	LAR681	<b>Reg Expiry:</b>	13 Jun 2025	Engine			·
WoF Expiry:	13 Jul 2025	Odometer:	173,819 Kms	Good No:	26506721	Oil level	~		
VIN:	7AT0C12HX17179036	Next Service:	174240km	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	S		S P P			Performance	~		
Key:	L'	-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust				715	HIL SW	Operation	~		
PT = paint defe				$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack				+	PT	Clutch			~
P = pin dent	HID				게	CV joints	~		
* = decals	sc 916			-No-	ALC S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W S P S S S S S S S S S S S S S S S S S						Performance	~		
Dadular		Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	•	of tyre	L
								mm	
						Right front	5		mm
						Left rear	5		mm
Conditions Duving Rody Inspection.						Right rear	5		 mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	•	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories			
						Head lights	~		
Jeals	Good					Tail lights	~		
Carpets	Good					Indicators	v v		
						Dashboard warning lights	v v		$\left  - \right $
Panels	ok besides	s wear and tear o	n steering wheel			Wipers (front & rear)	v v		
Dashboa	rd Good					Window winder FL	v v		
						Window winder FL	<i>v</i> <i>v</i>		
General (	Comments					Window winder FR			
						Window winder RL	マ マ		
Vehicle dro	ve well.					Rear view mirrors			
							V ./		
						Radio (basic test only)	<b>v</b>		
						CD (basic test only) Number of keys	1		L
							1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	<b>v</b>		
Engine Tir	ming Mechanism:	Timing (	Chain			Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera			~
Inspected by: Aaron Johnson Date: 07 Jan 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....