

Basic Vehicle Condition Guide

Report ID: 26,507,469

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Coolant condition

Created: 09 Jan 2025

Pass

~

~

/


Fail

N/A

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2020 Registration: NEN396 **Reg Expiry:** 28 Nov 2025 WoF Expiry: **Odometer:** 16 Jan 2026 97,947 Kms **Good No:** 26507469 VIN: KMHS281HWMU348924 **Next Service:** 101588 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

Kms:

Name:

General Comments

Partial service history

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Inspected by: Lukin Koveskali

Performance Radiator / Hoses (visual) Transmission Operation Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front 8 mm Left rear 5.0 mm Right rear 5.0 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR 1 Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) ~ CD (basic test only) 1 Number of keys 2 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera

29 Dec 2024

Signature:

Date:

				11.1	
have read	and un	aerstooa	this co	ondition	annae