

Basic Vehicle Condition Guide

Report ID: 26,507,891


3 Version:

27 Dec 2024 Created:

Make: Model: Volkswagen Golf **Body Style:** Hatchback Year: 2004 Registration: FLP526 Reg Expiry: 03 Jul 2025 **Odometer:** WoF Expiry: 11 Jun 2025 155,431 Kms **Good No:** 26507891 WVWZZZ1JZ3U552707 VIN: Next Service: 158000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Both mirror casings need paint, has a flat battery needed jump start,

Conditions During Body Inspection:

Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leak, minor underbody surface rust,

Interior Comments	<u>S</u>
Seats	wear,worn,minor stains ,
Carpets	wear,worn,minor stains ,
Panels	hood lining coming off ,
Dashboard	Average

General Comments

Drives okay, flat battery,

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Kms: No

> 27 Dec 2024 Date:

_	T	
Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
~		
~		
depth	of tyre	es)
5	.9	mm
6	.0	mm
5	.1	mm
4	.9	mm
	Yes	
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
V		
	~	
	<i>V</i>	
	<i>V</i>	
V	<i>V</i>	
2	\(\sigma \)	
2	V V	
2	v v	V
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

I have read and understood this condition guide.

Donovan Matara

Name [,]			