

|   |  | Coolant condition            | ~     |         |     |
|---|--|------------------------------|-------|---------|-----|
| No.   |  | Performance                  | ~     |         |     |
| S = scratch   |  | Radiator / Hoses (visual)    | ~     |         |     |
|   |  | Transmission                 |       |         |     |
| R = rust SC SS       |  | Operation                    | ~     |         |     |
| PT = paint defect                                     |  | Noise                        | ~     |         |     |
| C = crack   | SC   | Clutch                       |       |         | ~   |
| P = pin dent  |  | CV joints                    | ~     |         |     |
| ecais PID S   |  | Wheel bearings               | ~     |         |     |
| SC = stone chips<br>W = significant scuffs            |  | Brakes                       |       |         |     |
|   | S S S S  | Performance                  | ~     |         |     |
| Body Inspection C                                     | Note: some defects & blemishes may not be displayed in the diagram | Hand Brake                   | ~     |         |     |
|   |  | Tyres (lowest observed tread | depth | of tyre | es) |
| Missing tools/rf step p                               | late gouge marks   | Left front                   | 9.5   |         | mm  |
|   |  | Right front                  | 9.    | .5      | mm  |
|   |  | Left rear                    | 8.    | .5      | mm  |
| Conditions During Body Inspection: Dry                |  | Right rear                   | 8.    | .5      | mm  |
|   |  | Spare                        | Yes   |         |     |
| Under Carriage & Under Bonnet Inspection Comments     |  | Suspension                   |       |         |     |
| 2wd   |  | Suspension performance       | ~     |         |     |
|   |  | Steering performance         | ~     |         |     |
|   |  | Shock absorbers              | ~     |         |     |
|   |  | Air Conditioning / Heater    |       |         |     |
|   |  | Operation                    | ~     |         |     |
| Interior Comments                                     |  | Electrical / Accessories     |       |         |     |
| Seats   | worn marks   | Head lights                  | ~     |         |     |
|   |  | Tail lights                  | ~     |         |     |
| Carpets   | Average  | Indicators                   | ~     |         |     |
| Panels  | gouge mrks   | Dashboard warning lights     | ~     |         |     |
|   |  | Wipers (front & rear)        | ~     |         |     |
| Dashboard   | Average  | Window winder FL             | ~     |         |     |
| L   |  | Window winder FR             | ~     |         |     |
| General Comments                                      |  | Window winder RL             | ~     |         |     |
|   |  | Window winder RR             | ~     |         |     |
|   |  | Rear view mirrors            | ~     |         |     |
|   |  | Radio (basic test only)      | ~     |         |     |
|   |  | CD (basic test only)         | ~     |         |     |
|   |  | Number of keys               | 2     |         |     |
| Road Conditions During Test Drive: Dry                |  | Central locking              | ~     |         |     |
|   |  | Remote locking               | ~     |         |     |
| Engine Timing Mee                                     | Sat. Nav. (basic test only)  | ~                            |       |         |     |
| Evidence of Cam Belt Replacement: Not Applicable Kms: |  | Reversing camera             | ~     |         |     |
| la su             | ah Pepene  |                              | 24    |         |     |
| Inspected by: Uria                                    | Date: 31 Dec 20  | 24                           |       |         |     |
|   |  |                              |       |         |     |

I have read and understood this condition guide.

Name: .....

Signature: .....

Report ID: 26,508,426

Pass

V

V

V

V

Version:

Created:

1

31 Dec 2024

Fail

N/A