

Report ID: 26,508,555 1 Version: 03 Jan 2025 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A	
Year:	2018	Registration:	LQD135	Reg Expiry:	10 Mar 2025	Engine				
WoF Expiry:	13 Sep 2025	Odometer:	252,089 Kms	Good No:	26508555	Oil level	~			
VIN:	MNTCB2D23A0012512	Next Service:	261000	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Noise	~			
						Cooling System				
						Coolant condition	~			
	S		S S		S D	Performance	~			
Key:						Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission	Transmission			
D = dent R = rust PT = paint defect C = crack						Operation	~			
						Noise	~			
						Clutch	~			
P = pin dent						CV joints			~	
"= decais						Wheel bearings	~			
SC = stone chips W = significant scuffs S S S S S						Brakes				
						Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		r		
						Tyres (lowest observed tread depth of tyres)			es)	
LH tail light cracked Rear bumper Left cracked/ rear bumper right dent						Left front	ront 10.5		mm	
Right front seat pad torn/damaged						Right front	10).5	mm	
Stone chips on front windscreen						Left rear	6	.5	mm	
Conditions During Body Inspection: Wet						Right rear	6.5 m		mm	
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Rear wheel	drive					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories		-		
Seats	Poor					Head lights	~			
Carpets	A					Tail lights		~		
	Average					Indicators	~			
Panels	Average					Dashboard warning lights	~			
Dashboa	rd C					Wipers (front & rear)	~			
	rd Good					Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u>					Window winder RL	~				
Hand brake needs adjustment						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2			
Road Conditions During Test Drive: Wet						Central locking	~			
Enging Ti	ning Machanism	Timeline	Chain			Remote locking	~			
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:									~	
	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspecter	Inspected by: Xinghui Lin Date: 03 Jan 2025									

I have read and understood this condition guide.

Name:

Signature: