

Report ID: 26,510,171 1 Version: 13 Jan 2025 Created:

Make:	Mazda	Model:	CX-9	Body Style:	SUV		Pass	Fail	N/A
Year:	2015	Registration:		Reg Expiry:	15 Jul 2025	Engine			L
WoF Expiry:		Odometer:	193,326 Kms	Good No:	26510171	Oil level	~		
VIN:	JM0TB10A5G0440893	Next Service:		Service Histor	y:	Smoke & fumes	~		
					,	Performance	~		
	port is not a warranty		6	. Danta kara a a	harry discovered and an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	nical inspection prior to	purchase and tl	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SSC S	-0	S SC S SC		s	Radiator / Hoses (visual)	~		<u> </u>
S = scratch						Transmission			
D = dent R = rust	S SC			715	HIL S	Operation	~		
PT = paint defe	ect NP			$\left[ \right] \left[ \right]$		Noise	~		
C = crack				$+ \mathbf{\nabla}$	SC	Clutch			~
P = pin dent	HIS				74114	CV joints	~		
* = decals	sc gle			-Jul		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan	S SC S		SC D S P		SC	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishe	s may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
						Left front	4	ŀ	mm
						Right front	4	ŀ	mm
						Left rear	2	2	mm
Conditions During Body Inspection:						Right rear	2 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments					Electrical / Accessories				
Seats	Good					Head lights	~		
Carpote	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	urd Caral					Wipers (front & rear)	~		
Dastibua	ord Good					Window winder FL	~		
						Window winder FR	~		
<u>General C</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
L						Number of keys	2		·
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		
Engine Tir	ming Mechanism:	Timing (	Chain			Remote locking	~		
	of Cam Belt Replac			Kms:		Sat. Nav. (basic test only)			~
	or cam beit nepide		lot Applicable	11113.		Reversing camera	~		
Inspected	d by: Oneplus East					Date: 17 Dec 20	24		
	•								

I have read and understood this condition guide.

Name: .....

Signature: .....