

Report ID: 26,510,185 1 Version: 29 Dec 2024 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Wagon		Pass	Fail	N/A
Year:	2009	Registration:	JCG200	Reg Expiry:	04 Feb 2025	Engine	1		I
WoF Expiry:	10 Oct 2025	Odometer:	329,759 Kms	Good No:	26510185	Oil level	~		
VIN:	7AT0C139X15106466	Next Service:	N/A	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
	S W		S D SC S P		S D PT P W	Performance	~		
Key:		-0	3030 31		JUNI	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	SPTW			715	SW	Operation	~		
PT = paint defe				$\left[ \left( \right) \right]$		Noise	~		
C = crack					S D SC	Clutch			~
P = pin dent	HIC HIC				7414	CV joints	~		
* = decals	PT SC 91			The second	ELD'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significant	S SC W		SDP SDW		S D W	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						<b>Tyres</b> (lowest observed tread depth of tyres)			es)
Hole in front left spot light lens						Left front 3.6 mr			mm
Dent on sill above right rear door Rear tyres wearing on inner edges						Right front	4.0 mr		mm
Moisture in right rear boot lid tail light					Left rear	2.9 mn		mm	
Conditions During Body Inspection: Dry					Right rear	3.2 mm		mm	
					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Engine oil seep, transmission oil weep						Suspension performance	~		
		.cp				Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Hoani Saunders Date: 29 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....