

Basic Vehicle Condition Guide

Report ID: 26,510,233


Version:

24 Dec 2024 Created:

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2017 Registration: **KRW357** Reg Expiry: 23 May 2025 **Odometer:** Good No: WoF Expiry: 23 Dec 2025 113,513 Kms 26510233 VIN: MMAYYKL10HH003547 Next Service: 123,000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Aftermarket flat deck fitted LH/R deck hinge broken off RH middle deck hinge broken off

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4wd

| <u>Interior Comments</u> | | | |
|--------------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Drivers seat base material & foam torn, Seats stainedd

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

24 Dec 2024 Andre Richardson Inspected by: Date:

| | Pass | Fail | N/A |
|------------------------------|----------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | v | | |
| Noise | ~ | | |
| Cooling System | • | • | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | • | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | • | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 9 | 9 | mm |
| Right front | 9 | | mm |
| Left rear | 9 | | mm |
| Right rear | 9 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | • | | • |
| Operation | ~ | | |
| Electrical / Accessories | • | | • |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | | ~ |
| Window winder RR | | | ~ |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | ~ | | |

I have read and understood this condition guide.

Name:

Signature: