

Report ID: 26,510,279 11 Version: 08 Jan 2025 Created:

Year: 2015 Registration: JKF880 Reg Expiry: 11 Mar 2025 WoF Expiry: 23 Dec 2025 Odometer: 122,902 Kms Good No: 26510279 Oil level ✓ VIN: 1C4PJMFS5FW621428 Next Service: 132524 Service History: No Smoke & fumes ✓	1
VIN: 1040IMCSEFW62142C Next Service: 122524 Service History, No.	
VIN: 1C4PJMFS5FW62142{ Next Service: 132524 Service History: No Smoke & fumes 🖌	
Performance 🗸	
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or	
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends	
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	
Performance V	
Key: S = scratch Radiator / Hoses (visual)	
D = dent	·
R = rust Operation	
PT = paint defect Noise 🗸	
C = crack Clutch	~
P = pin dent	
* = decals Wheel bearings	
SC = stone chips W = significant scuffs	•
SC S D SC S D SC Performance	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Hand Brake	
Tyres (lowest observed tread depth of	of tyres)
· Left front 4.0	0 mm
Right front 4.0	0 mm
Left rear 3.5	5 mm
Conditions During Body Inspection: Dry Right rear 5.5	5 mm
Spare Spare	Yes
Under Carriage & Under Bonnet Inspection Comments Suspension	
Battery passed test Suspension performance 🖌	
Steering performance 🖌	
Shock absorbers 🖌	
Air Conditioning / Heater	
Operation 🖌	
Interior Comments Electrical / Accessories	
Seats Good Head lights 🖌	
Carpets Good Tail lights	
Carpets Good Indicators 🖌	
Panels Good Dashboard warning lights	
Dashboard Good	
Dashboard Good Window winder FL 🖌	
Window winder FR 🖌	
General Comments Window winder RL	
A/c, nav and reverse camera working at time of inspection. 95 octane petrol fuel. Window winder RR 🖌	
Rear view mirrors 🖌	
Radio (basic test only)	
CD (basic test only)	~
Number of keys 1	
Road Conditions During Test Drive: Dry	
Engine Timing Mechanism: Timing Chain	
Suidense of Cam Bolt Bonlasoment: Net And Statistic King:	
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera 🖌	
Inspected by: Reuben Harvey Date: 03 Jan 2025	

I have read and understood this condition guide.

Name:

Signature: