

Report ID: 26,511,206 2 Version: 08 Jan 2025 Created:

Make:	Suzuki	Model:	Vitara	Body Style:	SUV		Pass	Fail	N/A
Year:	2021	<b>Registration:</b>	NSM339	Reg Expiry:	15 Mar 2025	Engine		•	
WoF Expiry:	21 Jan 2026	Odometer:	40,971 Kms	Good No:	26511206	Oil level	~		
VIN:	TSMLYD21S00A2204(	Next Service:	53000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	or an additional C	narge.	Coolant condition	~		
						Performance	~		
Key:		=		5(0)-		Radiator / Hoses (vis	ual) 🖌		
S = scratch D = dent						Transmission			
R = rust				210		Operation	~		
PT = paint defe	ect NP				111/1	Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				74116	CV joints	~		
*= decals						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front	4	.0	mm
						Right front	4	.0	mm
						Left rear	4	.0	mm
Conditions During Body Inspection: Wet						Right rear	4	4.0 mm	
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension perform	ance 🖌		
						Steering performance	ce 🖌		
						Shock absorbers	~		
						Air Conditioning / He	eater		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning	lights 🖌		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test onl	y) 🖌		
						CD (basic test only)			~
						Number of keys	1	1	<u> </u>
Road Conditions During Test Drive: Wet						Central locking	~		
			**			Remote locking	· ·		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	· // ·		
Inspected	Inspected by: Greg Morgan Date: 27 Dec 2024								

I have read and understood this condition guide.

Name: .....

Signature: .....