

Report ID: 26,511,724 1 Version: 10 Jan 2025 Created:

Make:	Mazda	Model:	Premacy	Body Style:	Wagon		Pass	Fail	N/A
Year:	2008	<b>Registration:</b>	NQZ565	Reg Expiry:	12 Feb 2025	Engine	I	I	1
WoF Expiry:	22 Aug 2025	Odometer:	137,829 Kms	Good No:	26511724	Oil level	~		
VIN:	7AT0C133X19324715	Next Service:	overdue (134,000)	Service History	<b>/:</b> No	Smoke & fumes		~	
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation	~		
						Noise	~		
PT = paint defect C = crack						Clutch	•		~
P = pin dent						CV joints	~		
*=decals PT PIP						Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs						Performance	~		
Note: come defects % blamiches may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							· ·	ofture	
Paint peeling from bumpers. Headlights cloudy. Scrub marks below headlights. Paint faded bonnet and roof.						-	rres (lowest observed tread depth of tyres)		
Front bumper poor fit						Left front		3.5 n	
						Right front		.0	mm
						Left rear		7.0	
Conditions During Body Inspection: Dry						Right rear			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder carnage & onder bonnet inspection comments					Suspension				
Battery faile	ed test. Engine oil leaks.	Lhf tyre has edg	e wear			Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd A					Wipers (front & rear)	~		
	rd Average					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Radio n/w. No reverse camera or navigation. A/c working at time of inspection. No books. Oil fumes						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							<u> </u>	1	1
Inspected by: Reuben Harvey Date: 03 Jan 2025									
I have read and understood this condition guide. Name:									