

Report ID: 26,512,695 Version: 1 09 Jan 2025 Created:

Make:	Toyota	Model:	Starlet	Body Style:	Hatchback		Pass	Fail	N/A
Year:	1996	Registration:	CCL487	Reg Expiry:	23 Feb 2025	Engine	I		L
WoF Expiry:	21 Jun 2025	Odometer:	97,613 Kms	Good No:	26512695	Oil level	~		
VIN:	7A8H6110704155148	Next Service:	107,600kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0	S PT P	-161-	SP	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect C = crack P = pin dent C = pr f f						Transmission			
						Operation	~		
						Noise	~		
						Clutch	•		~
						CV joints	~		
* = decals SPT SC 919 SPT						Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs S PT SC S S PT P S PT P S PT						Performance 🖌			
						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	•	of tyre	
Cracks & chips off bottom edge of left front indicator lens.						Left front	5.0 mm		
						Right front		.0	 mm
						Left rear	5.		mm
Conditions During Pody Inspection						Right rear			 mm
Conditions During Body Inspection: Dry						Spare	7.0 mm Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
					Suspension performance	~			
Oil weeping from around bottom of cam belt cover on right side of engine block. Also oil weeping from between engine and gearbox.						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation	~		
Interior Comments						Electrical / Accessories	V		
Contr						Head lights	~		
Jeals	Average					Tail lights	~		
Carpets	Good					Indicators	~		
Deve alla						Dashboard warning lights	~		
Panels	Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL			
						Window winder FL Window winder FR	ン ン		
General Comments						Window winder FR Window winder RL	~		
						Window winder RE			~
Stitching starting to split on back rest of drivers seat.									~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Cambelt						Remote locking			~
Evidence of Cam Belt Replacement: Yes Kms: 60,000						Sat. Nav. (basic test only)			~
		iciniciniti î	C 3		,000	Reversing camera			~
Inspected by: Jason Young Date:									
I have read and understood this condition guide. Name:									