

Basic Vehicle Condition Guide

Report ID: 26,512,800


Version: 3

Created: 03 Jan 2025

Make: Model: Honda Accord **Body Style:** Sedan Year: 2009 Registration: NRG41 Reg Expiry: 27 Jan 2025 WoF Expiry: **Odometer: Good No:** 13 Jan 2026 96,675 Kms 26512800 VIN: 7AT08G13X21002256 **Next Service:** 106,909 Kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Rear tyres starting to wear on inner edges

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
	Seats	Slight wear on drivers seat		
	Carpets	Good		
	Panels	Good		
	Dashboard	Good		

General Comments

Left and right side rear seat head rests are missing

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Hoani Saunders Date: 30 Dec 2024

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v v		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	\(\triangle \)		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4	.8	mm
Right front	5.1		mm
Left rear	4.1		mm
Right rear	2.4		mm
Spare		N/A	
Suspension			
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater		1	
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	v		
Wipers (front & rear)			
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	1	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	'		

I have read and understood this condition guide.

Name:

Signature: