

Report ID: 26,512,816 Version: 1 10 Jan 2025 Created:

NA - 1-		M	<u> </u>	Dud Ci I	CLIN/			F ··	
Make:	Jeep	Model:	Grand Cherokee	Body Style:	SUV	Facine	Pass	Fail	N/A
Year: Wo F Fumimu	2007	Registration:	EDG802	Reg Expiry:	04 Jan 2025	Engine			<del></del>
WoF Expiry:		Odometer:	283,770 Kms	Good No:	26512816	Oil level	~		
VIN:	1J8HD68286Y156466	Next Service:	289,190kms	Service Histor	r <b>y:</b> No	Smoke & fumes	~		
Note: This re	port is not a warranty					Performance	~		
This report is	a guide only. Conside					Noise	~		
	sting undertaken. The vite sting undertaken. The vite states in the section prior to					Cooling System	1		
			-		-	Coolant condition	~		<u> </u>
Key:	SC S		S D P S		S	Performance	~		<u> </u>
S = scratch	~	$\sim$ (O)		(O)	$\checkmark$	Radiator / Hoses (visual)	~		
D = dent					AD IS	Transmission		1	
R = rust	s sc				HIV	Operation	~		
PT = paint defe	ect N				S D P SC	Noise	~		
C = crack						Clutch			~
P = pin dent	SPSC DI				~HHS	CV joints	~		
* = decals SC = stone chi		20		10	EP-S_	Wheel bearings	~		
W = significant scuffs						Brakes			
	S SC S	$\sim$	S S	S	S P	Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishe	s may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Rust developing along rear roof panel seam, on inside of tailgate frame. Left head rest on rear seat will not stay locked back, keep folding forward.						Left front	Left front 4.8 n		
stuy locaeu	bucky keep fording for					Right front	5	.0	mm
						Left rear	5	.0	mm
Conditions During Body Inspection: Dry						Right rear	5	.2	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil weening	g from between engine	& gearbox				Suspension performance	~		
on weeping	g nom between engine	a gearbox.				Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		Τ
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		1
						Wipers (front & rear)	~		1
Dashboa	rd Good					Window winder FL	~		1
•	•					Window winder FR	~		1
General Comments						Window winder RL	~		1
Centre right dash air vent has a fin that is broken & missing.						Window winder RR	~		1
5			2			Rear view mirrors	~		+
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)			~
						Number of keys	2	I	<u> </u>
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		1
						Remote locking	· ·		+
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		+
	•	-					-		<u> </u>
Inspected	d by: Jason Young					Date: 10 Jan 20	25		
have read	and understood th	is condition c	uide. Name:			Signature:			