

Report ID: 26,513,914 1 Version: 06 Jan 2025 Created:

Make:	Subaru	Model:	XV	Body Style:	Wagon		Pass	Fail	N/A
Year:	2014	Registration:	PEH399	Reg Expiry:	28 Mar 2025	Engine	I	1	1
WoF Expiry:	30 Dec 2025	Odometer:	114,000 Kms	Good No:	26513914	Oil level	~		
VIN:	7AT0GF1XX22020573	Next Service:	01/01/24	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		+
Key:	SC	-0		-161-		Radiator / Hoses (visual)	v		
S = scratch						Transmission			L
D = dent						Operation	~		
R=rust						Noise	~		
PT = paint defect C = crack						Clutch	•		~
P = pin dent	Ho					CV joints	~		
* = decals	sc PIK			AL.	EITR	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs S						Performance	~		1
						Hand Brake			
Body Inspection Comments								ofture	
Good						Tyres (lowest observed tread depth of tyres)			
						Left front	7 mm 7 mm		
						Right front			mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare No			
onder carriage & onder bonnet inspection comments						Suspension			
Rocker cove	er gasket leak					Suspension performance	~		
						Steering performance	~		<u> </u>
						Shock absorbers	~		
		Air Conditioning / Heater							
Interior Comments						Operation			~
						Electrical / Accessories	1		
Seats	cigarette k	ourns				Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights		~	
Dashboa	rd Cood					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Front tyre pressures low						Window winder RR	~		
Left wing mirror does not fold in Fault in eye sight system, multiple dash warning lights on						Rear view mirrors		~	
Fault in eye	sight system, multiple	uash warning ng				Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	-		-			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Hana Cotter Date: 06 Jan 2025									
I have read and understood this condition guide. Name:									