

Report ID: 26,513,922 1 Version: 07 Jan 2025 Created:

Make:	Honda	Model:	Elysion	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2007	<b>Registration:</b>	KDQ817	Reg Expiry:	04 Aug 2025	Engine	I	L	I	
WoF Expiry:	14 Aug 2025	Odometer:	207,519 Kms	Good No:	26513922	Oil level	~			
VIN:	7AT08GBPX16003093	Next Service:	205900	Service Histor	<b>y:</b> No	Smoke & fumes		~		
						Performance	~	-		
	port is not a warranty		for one and miles as	Danta hava nat	heen discontined or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:	IS W	-0	SP SP		SP	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	SD 6/6			The	EII S	Operation	~			
R = rust PT = paint defe				í In	JHH	Noise	~			
C = crack					РТ	Clutch			~	
P = pin dent	HC					CV joints	~		•	
* = decals	s PIK			- AL	EIIP I	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S W S P S P W S						Performance V				
		Note: son	Le defects & blemisbes	may not be disr	laved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	oftyre	) )	
Windscreen chip						Tyres (lowest observed tread depth of tyres)           Left front         5			mm	
Front bumper alignment						Right front		5	-	
						Left rear			mm mm	
								5		
Conditions During Body Inspection:						Right rear   5   mm     Spare   Vec			mm	
Under Carriage & Under Bonnet Inspection Comments					Spare Yes Suspension					
						Suspension performance				
Oil leaks							~			
						Steering performance	~			
						Shock absorbers	~			
<u> </u>						Air Conditioning / Heater				
Interior Comments						Operation		~		
						Electrical / Accessories				
Seats	Average					Head lights	~			
Carpets	Average					Tail lights	~			
						Indicators	~			
Panels	Average					Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	~			
						Window winder FL	~			
General	omments					Window winder FR	~			
<u>General Comments</u>					Window winder RL	~				
Air conditioning not working Smoke / fumes noted on road test						Window winder RR	~			
Sinoke / Iui	nes noted on road test					Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2			
Road Conditions During Test Drive:     Dry     Central locking							~			
Engine Ti	ming Mechanism:	Cambel				Remote locking	~			
Sal. Ivav.									~	
Evidence	or Carri Deit Replac	ement: Y	es	Kms: 14	ł∠,ŏU4	Reversing camera	~			
Inspected	Inspected by: Kilipati Mae Date: 07 Jan 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....