


| | | |
|--------------------------------|------------------------------|--------------------------------|
| Make: Toyota | Model: IST | Body Style: Hatchback |
| Year: 2003 | Registration: EUB684 | Reg Expiry: 22 Mar 2025 |
| WoF Expiry: 05 Jan 2025 | Odometer: 219,043 Kms | Good No: 26513967 |
| VIN: 7A8H6470709068436 | Next Service: N/A | Service History: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

- Surface rust in spare wheel well
- Stone chips in front windscreen
- Both front wheel hub caps are cracked
- Front bumper left side lower plastic trim is missing

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Rust on of spare wheel well to the point there is a hole about 50mm wide

Interior Comments

| | |
|-----------|---------------------------|
| Seats | Good |
| Carpets | Large rip on drivers side |
| Panels | Good |
| Dashboard | Good |

General Comments

Key remote is missing key stalk

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A |
|---|------|------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Performance | ✓ | | |
| Noise | ✓ | | |
| Cooling System | | | |
| Coolant condition | ✓ | | |
| Performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand Brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 5.2 | mm | |
| Right front | 3.7 | mm | |
| Left rear | 2.1 | mm | |
| Right rear | 2.9 | mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 2 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. Nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

Inspected by: Hoani Saunders

Date: 03 Jan 2025

I have read and understood this condition guide. Name: Signature: