

Report ID: 26,514,325 2 Version: 06 Jan 2025 Created:

Make:	Mazda	Model:	Verisa	Body Style:	Hatchback		Pass	Fail	N/A	
	2005	Registration:	MDF544	Reg Expiry:	19 Nov 2025	Engine			I	
WoF Expiry:	26 May 2025	Odometer:	123,716 Kms	Good No:	26514325	Oil level	~			
VIN:	7AT0C103X18205816	Next Service:	129000 kms	Service Histor	V: No	Smoke & fumes	~			
						Performance	~			
	oort is not a warranty		6	Dauta have used		Noise	V			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechani	cal inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~			
		_		-		Performance	~			
Key:	SC S	-0	S D		Р	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	s sc 6/6			The	EID S	Operation	~			
R = rust				10	THIA	Noise	~			
PT = paint defe C = crack				+		Clutch	•		~	
P = pin dent						CV joints	~		•	
* = decals	PSC PIC			AL.		Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SC S P SP S S SP						Performance	~			
		Note: com	ne defects & blemishes	may not be disp		Hand Brake	~			
Body Insp	ection Comments	10000.3011	le delects & blemisnes	illay liot be disp	layed in the diagram		•	- f t wa		
Roof faded.						Tyres (lowest observed tread depth of tyres)				
						Left front	2.		mm	
						Right front	2.		mm	
						Left rear	2.		mm	
Conditions During Body Inspection: Dry						Right rear	3.5 mm		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
	nage & onder bor	<u>ince inspectie</u>	<u>in comments</u>			Suspension			1	
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
						Electrical / Accessories				
Seats	Average					Head lights	~			
Carpets	Average					Tail lights	~			
	, weitige					Indicators	~			
Panels	Average					Dashboard warning lights	~			
Dashboar	rd Average					Wipers (front & rear)	~			
						Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
Air Con fan s	stuck on high. Air Con v	vorks but only g	ets to 10 degrees.			Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry							~			
			cı ·			Remote locking	~			
-	ning Mechanism:	Timing (Sat. Nav. (basic test only)			~	
Evidence of	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
	Inspected by: Chris McQuade Date: 06 Jan 2025									
Inspected by: Christiane Date: 00 Jail 2025										

I have read and understood this condition guide.

Name:

Signature: