

| Make: | Mini | Model: | Cooper | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--------------------|----------------------|----------------|----------------|--------------|--|------|------|-----|
| Year: | 2005 | Registration: | MAT844 | Reg Expiry: | 10 Sep 2025 | Engine | | | |
| WoF Expiry: | 27 May 2025 | Odometer: | 68,217 Kms | Good No: | 26514450 | Oil level | ~ | | |
| VIN: | WMWRC32070TJ24906 | Next Service: | 72,000kms | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | ~ | | |
| | SC | | S | | Р | Performance | ~ | | |
| Key: | | = | | 5(0)- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent R = rust S SC S D PT | | | | | | Transmission | | | |
| | | | | | | Operation | ~ | | |
| PT = paint defect | | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | | | | | | CV joints | ~ | | |
| * = decais | | | | | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | 1 |
| W = significant scuffs S P P | | | | | | Performance 🖌 | | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | Hand Brake | v | | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| Chrome surround missing off right front spot light in front bumper. | | | | | | Left front | 3.2 | | mm |
| | | | | | | Right front | 3.2 | | mm |
| | | | | | | Left rear | 2. | .4 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 3. | .6 | mm |
| | | | | | | Spare N/A | | | |
| Under Carriage & Under Bonnet Inspection Comments Oil weeping around bottom right side, timing chain cover area & around engine sump pan. Power steering hoses weeping where they connect down to steering rack. | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | | | | | | Tail lights | ~ | | |
| Carpets | Good | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments Both front tyres are not run flats, as both rear tyres are run flats. Vehicle should have all tyres as run flats. | | | | | | Window winder RL | | | ~ |
| | | | | | | Window winder RR | | | ~ |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Jacob Stad by Jacob Voung | | | | | | | | | |
| Inspected by: Jason Young Date: 09 Jan 2025 | | | | | | | | | |
| I have read and understood this condition guide. Name: | | | | | | | | | |