

Basic Vehicle Condition Guide

Report ID: 26,514,581


Version:

Created: 08 Jan 2025

Make: Model: Suzuki Jimny **Body Style:** SUV Year: 2020 Registration: NCJ573 Reg Expiry: 27 Jun 2025 **Odometer:** WoF Expiry: **Good No:** 06 Nov 2025 50,195 Kms 26514581 VIN: **Next Service:** JSAGJB74V00160640 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Stone chips front window screen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

No underbody inspection

4x4 untested

| <u>Interior Comments</u> | | | |
|--------------------------|--------------------------------------|--|--|
| Seats | small wear holes drivers seat, marks | | |
| Carpets | marks, wear | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Melissa Wilson Date: 08 Jan 2025

Name:

| | Pass | Fail | N/A | |
|------------------------------|--|---------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\triangle \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | V | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | • | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | ~ | | | |
| CV joints | \(\times \) | | | |
| Wheel bearings | ~ | | | |
| Brakes | • | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | 9 | 9 | mm | |
| Right front | 6.4 | | mm | |
| Left rear | 7.6 | | mm | |
| Right rear | 7.4 | | mm | |
| Spare | Yes | | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | \(\times \) \(\t | | | |
| Window winder FR | ~ | | | |
| Window winder RL | | | ~ | |
| Window winder RR | | | ~ | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | | | ~ | |
| Number of keys | 2 | 1 | 1 | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | ~ | | | |
| Reversing camera | | | ~ | |
| | | | | |

Signature: