

Report ID: 26,514,926 3 Version: 10 Jan 2025 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2016	Registration:	JZL772	Reg Expiry:	12 Jan 2025	Engine			
WoF Expiry:	14 Jun 2025	Odometer:	108,936 Kms	Good No:	26514926	Oil level	~		
VIN:	MMU148EK0GH653909	Next Service:	14/12/24 or 110000km	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	S		SP SP		S	Performance	~		
Key:	L'ALL	-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch	~		<u> </u>
P = pin dent	HIC				ᅰЦ	CV joints	~		<u> </u>
*= decals SC 919 S						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S D P S S S D P S						Performance	~		
Redulars a stress of the diagram Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		+
Body Inspection Comments						Tyres (lowest observed tread	•	of tvre	⊥ ≥s)
						Left front	5		mm
						Right front	5		mm
						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	5		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
All good.						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories	·		
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		<u> </u>
	Good					Wipers (front & rear)	~		+
Dashboa	rd Good					Window winder FL	~		<u> </u>
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
Vehicle drove well.						Window winder RR	~		<u> </u>
venicie dio	ve wen.					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	•		~
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	2 1		
KOAG CON	ations During Tes	t Drive:	Dry			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			<i>v</i> <i>v</i>
		•	-						
Inspecte	d by: Jayden Roxburg	Date: 10 Jan 202	25						
I have read	and understood th	is condition c	uide. Name:			Signature:			