

Report ID: 26,515,319 1 Version: 10 Jan 2025 Created:

Make:	BMW	Model:	1 Series	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	Registration:	JJH633	Reg Expiry:	21 May 2025	Engine			
WoF Expiry:	25 Nov 2025	Odometer:	135,260 Kms	Good No:	26515319	Oil level	~		
VIN:	WBA1A12030J208921	Next Service:	138,000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for and milages	Darte have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
		_				Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
						Operation	~		
R = rust PT = paint defe				\prod	JHIH	Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints			~
*=decals SC 919						Wheel bearings	~		•
SC = stone chips							Brakes		
W = significant scuffs						Performance	~		
		Note: som	e defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	oftyre	c)
Vehicle has emergency tire inflation device.									mm
						Right front	8.	-	mm
						Left rear			mm
			_					-	
Conditions During Body Inspection: Dry						Right rear 7.0 mm Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Vehicle has belly pans. Runs on 95/98 octane fuel. Tested battery and passed						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
Interior Comments						Operation 🖌			
Seats	marks					-	~		
Carpets	Average					Tail lights Indicators	~		
							~		
Panels	scratches	scuffs marks				Dashboard warning lights	v		
Dashboa	rd Average					Wipers (front & rear)	v		
	J -					Window winder FL	v		
General (<u>Comments</u>					Window winder FR Window winder RL	v		
Air conditioning and heating systems temperature good and reverse camera fine at inspection						Window winder RL Window winder RR	v		
Air conditio	ning and heating syste	ms temperature	good and reverse cam	iera fine at inspe	tion	Rear view mirrors	v		
							~		
						Radio (basic test only)	~		
						CD (basic test only) Number of keys			
Deed Canditiana During Test Driver						-	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Tir	ming Mechanism:	Timing (hain			Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
				11113.		Reversing camera	~		
Inspected by: Gary Adams Date: 07 Jan 2025									

I have read and understood this condition guide.

Name:

Signature: