


<b>Make:</b> Suzuki	<b>Model:</b> Swift	<b>Body Style:</b> Hatchback
<b>Year:</b> 2004	<b>Registration:</b> DMN618	<b>Reg Expiry:</b> 30 Jun 2025
<b>WoF Expiry:</b> 06 May 2025	<b>Odometer:</b> 225,001 Kms	<b>Good No:</b> 26515498
<b>VIN:</b> 7A8GK0C0706100554	<b>Next Service:</b> 3-5-24	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Rocker cover gasket recommended to be replaced — oil residue around the top of the engine. Oil needs to be serviced. Coolant top up. Brake makes a slight screeching. General scratches and sun fades around the body of the vehicle.

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Front inner CV boots seepage. Oil leaks underneath could be due to the rocker cover further investigation required.

Interior Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

No comment.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown  
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front	4	mm	
Right front	6	mm	
Left rear	4	mm	
Right rear	6	mm	
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking		✓	
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Jesh Singh

Date: 09 Jan 2025

I have read and understood this condition guide. Name: ..... Signature: .....