

Basic Vehicle Condition Guide

Report ID: 26,516,218


Version: 2

Created: 05 Jan 2025

Make: Model: Mazda Atenza **Body Style:** Wagon Year: 2011 Registration: **QZY868** Reg Expiry: 05 Feb 2025 **Odometer:** WoF Expiry: 09 Dec 2025 156,579 Kms **Good No:** 26516218 VIN: **Next Service:** 7AT0C139X16726439 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Underbody corrosion

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Kilipati Mae Date: 05 Jan 2025

Name:

	Pass	Fail	N/A
Engine		1	
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System		1	
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission		1	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		1	
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	deptl	n of tyre	es)
Left front		4	mm
Right front	4		mm
Left rear	5		mm
Right rear		5	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		1	
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	/		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		1
Central locking	/		
Remote locking	~		
Sat. Nav. (basic test only)			'
Reversing camera			'

Signature: