

Report ID: 26,516,260 1 Version: 05 Jan 2025 Created:

Make:	Volkswagen	Model:	Golf	Body Style:	Wagon		Pass	Fail	N/A
Year:	2014	<b>Registration:</b>	PRB943	Reg Expiry:	05 May 2025	Engine	1		I
WoF Expiry:	11 Mar 2025	Odometer:	101,560 Kms	Good No:	26516260	Oil level	~		
VIN:	WVWZZZAUZFP526231	Next Service:	107000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	S		Р		S	Performance	~		
Key:	L'ALL	-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			I
D = dent R = rust				715	HIVS	Operation	~		
PT = paint defe				$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack					S P	Clutch			~
P = pin dent	sc dle				74 <u>11</u> 4	CV joints	~		
						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S P						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front 4			mm
						Right front	4	1	mm
						Left rear	3	3	mm
Conditions During Body Inspection:						Right rear	3	3	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2	2	
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
Inspected by: Kilipati Mae Date: 05 Jan 2025									
Inspected by: Kilipati Mae Date: 05 Jan 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....