

Basic Vehicle Condition Guide

Report ID: 26,516,294


Version:

09 Jan 2025 Created:

Make: Model: Honda Jazz **Body Style:** Hatchback Year: 2018 Registration: LDF107 Reg Expiry: 26 Jun 2025 **WoF Expiry: Odometer: Good No:** 12 Jan 2026 79,796 Kms 26516294 VIN: JHMGK5830JX202444 Next Service: 89,774Kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

FWD

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

09 Jan 2025 **Bobby Zhong** Inspected by: Date:

| | Pass | Fail | N/A | |
|------------------------------|------------------|---------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\times \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | V | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | • | • | • | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | | 7 | mm | |
| Right front | 7 | | mm | |
| Left rear | 7 | | mm | |
| Right rear | 7 | | mm | |
| Spare | N/A | | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | V | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | <i>'</i> | | | |
| Wipers (front & rear) | 1/ | | | |
| Window winder FL | 1/ | | | |
| Window winder FR | V V V V | | | |
| Window winder RL | 1 | | | |
| Window winder RR | | | | |
| Rear view mirrors | V | | | |
| | | | | |
| Radio (basic test only) | V | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | ' | | | |
| Remote locking | ' | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |

I have read and understood this condition guide.

Name:

Signature: