

Report ID: 26,516,358 Version: 1 08 Jan 2025 Created:

Make:	Subaru	Model:	Legacy	Body Style:	Sedan		Pass	Fail	N/A
Year:	1999	Registration:	EYG82	Reg Expiry:	05 Jan 2025	Engine	1	I	1
WoF Expiry:	09 Apr 2025	Odometer:	242,083 Kms	Good No:	26516358	Oil level	~		
VIN:	7A8GF0B0708010514	Next Service:	Unknown	Service Histor	y: No	Smoke & fumes	~		
						Performance	r		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	SSC S	-0	S D PT SC S D SC		S D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent PT C SC PT SC S PT SC						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	~		
P = pin dent						CV joints	~		
* = decals SPT SC 919 SSC						Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs S SC W P SC D SC S D PT SC						Performance	~		
		Note: son		may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	oftur))
Front number plate bent to fit.						Tyres (lowest observed tread depth of tyre			
LH mirror surround damaged.						Left front		.5	mm
						Right front		5	mm
						Left rear	7		mm
Conditions During Body Inspection: Dry						Right rear	6.5 mm		mm
Under Carriage & Under Pennet Increation Comments						Spare No			
Under Carriage & Under Bonnet Inspection Comments Engine oil leak.						Suspension			
						Suspension performance	~		
Rear differe	ntial seepage.					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Poor, front	t seats torn.				Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average, s	hift knob fits poo	orly.			Dashboard warning lights	~		
Deskie	rd 6					Wipers (front & rear)		~	
Dashboa	ru Average, s	teering wheel w	earing.			Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Short clutch pedal travel. Rear window washer fail.						Window winder RR	~		
Key works in ignition only, no key for door or boot locks.						Rear view mirrors		~	
Missing spare wheel.HVAC temperature control knob faulty.LH mirror doesn't retract.Steering column surrounds missing.						Radio (basic test only)	~		
			o a do 111051119.			CD (basic test only)			~
						Number of keys	1	1	
Road Conditions During Test Drive: Dry Central locking							~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt Sat. Nav. (basic test									~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
							1	1	I
Inspected by: Troy Smith Date: 08 Jan 2025									

I have read and understood this condition guide.

Name:

Signature: