

Report ID: 26,517,875 1 Version: 09 Jan 2025 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2013	Registration:	PSC839	Reg Expiry:	18 Jan 2025	Engine			
WoF Expiry:	23 Feb 2025	Odometer:	74,000 Kms	Good No:	26517875	Oil level	~		
VIN:	7AT0C139X22102827	Next Service:	16/12/2023	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside		for age and mileage	e. Parts have not	been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechai	lical inspection phor to	purchase and ti	lis can be arranged i		Lharge.	Coolant condition	~		
		\sim	S			Performance	~		
Key: S = scratch		\sim (0)		5(0)-		Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	s Alb			10		Operation	~		
PT = paint def	ect NIC	1				Noise	~		
C = crack				TT		Clutch			~
P = pin dent	s sc dl				~848	CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	S	\sim	SC		S	Performance	~		
Body Ins	pection Comments	Note: som	ne defects & blemishe	es may not be disp	blayed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			es)
ok						Left front 4		1	mm
						Right front	4	1	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
ok						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	good					Head lights	~		
Carpets	average					Tail lights	~		
	uverage					Indicators	~		
Panels	good					Dashboard warning lights	~		
Dashboa	rd good					Wipers (front & rear)	~		
	9000					Window winder FL	~		
Gonoral	Commonts					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Needs servi	ice					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
		.cmcnt. N	10	11113.		Reversing camera	~		
Inspected by: My autoshop Date: 08 Jan 2025									

I have read and understood this condition guide.

Name:

Signature: