

## **Basic Vehicle Condition Guide**

Report ID: 26,518,870

Version: 3

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Left rear

Right rear

Suspension

Suspension performance

Steering performance

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL
Window winder FR

Window winder RL
Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Shock absorbers

Air Conditioning / Heater

Operation

Head lights
Tail lights
Indicators

Spare

Right front

Coolant condition
Performance

Radiator / Hoses (visual)

Created: 07 Jan 2025

Pass

1

V

/

V

1

Tyres (lowest observed tread depth of tyres)

N/A

1

mm

mm

mm

mm

8

9

1

/

/

/

1

1

1

~


Yes

Fail

Make: Hyundai Model: lx35 **Body Style:** SUV Year: 2015 Registration: HYZ209 **Reg Expiry:** 26 Feb 2025 **WoF Expiry: Odometer:** 16 Dec 2025 165,633 Kms **Good No:** 26518870 KMH IT81FMFU046387 VIN: **Next Service:** 170516 kms **Service History:** Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Fwd

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Good			

## **General Comments**

Driver seat torn, steering wheel worn, missing spare tools, boot body seal torn, R rear interior door panel.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

I have read and understood this condition guide.

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Marlon Espena Date: 07 Jan 2025

Name:	 Signature:	