

Report ID: 26,519,330 Version: 1 07 Jan 2025 Created:

Make:	Peugeot	Model:	307	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	Registration:	DBY554	Reg Expiry:	23 Jul 2025	Engine			<u> </u>
WoF Expiry:	23 Jun 2025	Odometer:	233,410 Kms	Good No:	26519330	Oil level	~		
VIN:	VF33CRFJF84366770	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		-
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		1
						Performance	~		
Key:		-0	S D			Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			The	Transmission	•		
D = dent	GIE			The		Operation		~	
R = rust				10	JHIA	Noise	~	v	-
PT = paint def C = crack				+	PT	Clutch			~
P = pin dent	Ho	KI			JUII —	CV joints	~		
* = decals	- MIK			AL-	ENR	Wheel bearings	-		
SC = stone chips							•		
W = significant scuffs W PT PT W						Brakes Performance			
Note: come defects % blomiches may not be displayed in the diagram							~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<i>с</i> .	
						Tyres (lowest observed tread		,	-
						Left front		.0	mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear	6.0 m		mm
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
	mage & Under BOI	inet inspectio	<u>on comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			1
Seats	left rear se	atbelt webbing	damage			Head lights	~		
Carpets	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd A					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Harsh shifting						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Greg Morgan Date: 07 Jan 2025									
I have read and understood this condition guide. Name:									