

Report ID: 26,519,896 4 Version: 11 Jan 2025 Created:

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A	
Year:	2012	<b>Registration:</b>	JTB695	Reg Expiry:	12 Sep 2025	Engine	1		L	
WoF Expiry:		Odometer:	313,131 Kms	Good No:	26519896	Oil level	~			
VIN:	KMHSH81XSCU831133	Next Service:	315,000 Kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~			
			DP		Р	Performance	~			
Key:		-0				Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
D = dent R = rust	s sc			210	S PT	Operation	~			
PT = paint defe					70111	Noise	~			
C = crack					SC	Clutch			~	
P = pin dent	sc dle				24116	CV joints	~			
* = decals		10		10	ED S	Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
W – significan			P		DP	Performance	~			
Body Insr	ection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)				
Stone chip in front windscreen						Left front	3.	.4	mm	
						Right front	4.	.3	mm	
						Left rear	3.	.4	mm	
Conditions During Body Inspection: Dry						Right rear	4.1 mm		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Slight wea	ar on drivers seat				Head lights	~			
Correcto						Tail lights	<			
Carpets	Good					Indicators	~			
Panels	Average					Dashboard warning lights	~			
Dashboa						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	۲			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	2			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected	Inspected by: Hoani Saunders Date: 09 Jan 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....