

Report ID: 26,520,894 1 Version: 09 Jan 2025 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Wagon		Pass	Fail	N/A
Year:	2012	Registration:	KQQ811	Reg Expiry:	03 Jul 2025	Engine			
WoF Expiry:	22 Jan 2026	Odometer:	163,004 Kms	Good No:	26520894	Oil level	~		
VIN:	7AT0C139X17203763	Next Service:	173,000kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
	S		S S		S	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s sc			210	S SC	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch	~		
P = pin dent	s sc				24114	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan	W		S			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	7.	0	mm
						Right front	7.	7	mm
						Left rear	6.	2	mm
Conditions During Body Inspection: Dry						Right rear	6.6 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
	_					Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpots	Coord					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Caral					Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet							~		
Enging Ti	ning Machanism	Timina	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:									~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Kyle Kelly Date: 08 Jan 2025									

Name: