

Report ID: 26,521,244 1 Version: 09 Jan 2025 Created:

Make:	Toyota	Model:	Century	Body Style:	Sedan		Pass	Fail	N/A
Year:	2000	Registration:	NRC748	Reg Expiry:	29 Jul 2025	Engine			
WoF Expiry:	27 Sep 2025	Odometer:	182,886 Kms	Good No:	26521244	Oil level	~		
VIN:	7AT0H61RX21004334	Next Service:	unknown	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional of	charge.	Coolant condition	~		
			P			Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	sc			210	HILLS	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					РТ	Clutch			~
P = pin dent	sc dl				24116	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front 7.0			mm
						Right front	7.	.0	mm
						Left rear	4.	.0	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine oil le	eaking from around bot	h side rocker cov	ver and reaching to ex	haust pipes.(Sme	ells burning oil).	Suspension performance	~		
	g					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	<		
Dashboa	rd c i					Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
	•					Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
No service record but current oil is not dirty.						Window winder RR	~		
CD changer cartridge is missing. Right rear passenger table is jammed.						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking							~		
Engine Ti	ning Machanian	T:	[°] hain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Yuki Itohara Date: 09 Jan 2025									

I have read and understood this condition guide.

Name:

Signature: