

Report ID: 26,522,662 Version: 1 Created: 11 Jan 2025

Make:	Toyota	Model:	Hiace	Body Style:	Van		Pass	Fail	N/A
Year:	2010	Registration:	MGG219	Reg Expiry:	05 Jan 2025	Engine			1
WoF Expiry:	20 Aug 2025	Odometer:	184,942 Kms	Good No:	26522662	Oil level	~		
VIN:	7AT0H60FX19004533	Next Service:	198,000 Kms	Service Histor	y: No	Smoke & fumes	~		1
	_					Performance	~		1
	port is not a warranty a quide only Consid		for age and mileage	Parts have not	been dismantled or	Noise	~		1
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
			S SSC		P SC	Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		<u> </u>
S = scratch	STE				Tan	Transmission			1
D = dent R = rust	sw bl	1		715	SD SD	Operation	~		1
PT = paint defe		IT I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		+
C = crack				+	S D	Clutch			~
P = pin dent	HIS				741L	CV joints			~
* = decals	PSC 916			- NL	ELLE W	Wheel bearings	~		<u> </u>
SC = stone chips						Brakes	•		<u> </u>
W = significant scuffs						Performance	~		<u> </u>
		Note: son	ne defects & blemishes	s may not be disc	blaved in the diagram	Hand Brake	~		+
Body Inspection Comments						Tyres (lowest observed tread	•	of tyre	 es)
Rear boot lid badge/emblem missing						Left front			
Crack in front windscreen and left rear tail light lens						Right front	4.		mm
						Left rear	4.		mm
Conditions During Pody Inspection:						Right rear			mm
Conditions During Body Inspection: Dry						Spare	4.6 mm Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
		·				Suspension performance	~		1
						Steering performance			
						Shock absorbers	ン ン		
						Air Conditioning / Heater	V		
		Operation	~		1				
Interior Comments						Electrical / Accessories	V		
Casta	Seats Rip on drivers seat					Head lights			T
Seals	Rip on dri	vers seat					~		
Carpets	Good					Tail lights	~		+
						Indicators	~		
Panels	Light scuf	fs				Dashboard warning lights	~		
Dashboa	rd Glovebox	lid needs to be s	ecured properly			Wipers (front & rear)	~		
			1 - F V			Window winder FL	~		
General	Omments					Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
Vehicle making unknown noise, advise to have checked						Window winder RR			~
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		<u> </u>
Enging Ti	ming Mechanism	Combol	+			Remote locking	~		<u> </u>
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 135,935						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	.ement: Y	′es	Kms: 13	35,935	Reversing camera			~
Inspected by: Hoani Saunders						Date: 10 Jan 2025			
inspecte	u by. Houri Saunder:								
I have read	and understood th	is condition o	uide Name			Signature:			