

Report ID: 26,524,223 1 Version: 09 Jan 2025 Created:

| Make: | Toyota | Model: | Aqua | Body Style: | Hatchback | | Pass | Fail | N/A |
|---|---|----------------------|------------------------|--------------------|----------------------|--|------|------|-----|
| Year: | 2014 | Registration: | MSZ503 | Reg Expiry: | 20 Jan 2025 | Engine | | | |
| WoF Expiry: | 17 Mar 2025 | Odometer: | 87,031 Kms | Good No: | 26524223 | Oil level | ~ | | |
| VIN: | 7AT0H65YX20326646 | Next Service: | 95000 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty a guide only. Conside | eration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| diagnostic tes | sting undertaken. The | ehicle has beer | n driven up to 50km/h | from cold. The | Vendor recommends | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | his can be arranged fo | or an additional o | charge. | Coolant condition | ~ | | |
| | | | S | W | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| B = rust | s dR | | | 710 | HIVS | Operation | ~ | | |
| PT = paint defe | | | | | 101h | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | s dR | | | | 74116 | CV joints | ~ | | |
| * = decals | | | | 10 | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| W – significant | S W | | S SP | | | Performance | ~ | | |
| Body Insr | ection Comments | Note: som | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | V | | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front 5 m | | | |
| | | | | | | Right front | | 5 | mm |
| | | | | | | Left rear | | 5 | mm |
| Conditions During Body Inspection: | | | | | | Right rear | 6 mn | | mm |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Comoto | | | | | | Tail lights | ~ | | |
| Carpets | Good | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> | | | | | Window winder RL | ~ | | | |
| Key fob not | working | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | _ | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | nin a Maalaa | | | | | Remote locking | | ~ | |
| - | ming Mechanism: | Timing (| | 14 | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Inspected | d by: Kilipati Mae | | | | | Date: 09 Jan 202 | 25 | | |
| | ~) | | | | | | - | | |

I have read and understood this condition guide.

Name:

Signature: