

Basic Vehicle Condition Guide

Report ID: 26,525,438


Version:

09 Jan 2025 Created:

Make: Model: Hyundai loniq **Body Style:** Hatchback Year: 2022 Registration: PME154 Reg Expiry: 22 Mar 2025 **Odometer:** WoF Expiry: 23 Sep 2025 21,175 Kms **Good No:** 26525438 **Next Service:** VIN: KMHC751JUNU087630 35173 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Damage on rear bumper

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Charge cable in boot

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

09 Jan 2025

	Pass	Fail	N/A	
Engine				
Oil level			~	
Smoke & fumes			~	
Performance			~	
Noise			~	
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	depth	of tyre	es)	
Left front	4	1	mm	
Right front	4		mm	
Left rear	4		mm	
Right rear	4		mm	
Spare		No		
Suspension	•			
Suspension performance	~			
Steering performance	V V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	V V V V V			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)			~	
Number of keys	1			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera	~			

I have read and understood this condition guide.

Kilipati Mae

Name:

Signature: