

Report ID: 26,526,574 4 Version: 15 Jan 2025 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2010	Registration:	FPB404	Reg Expiry:	12 Feb 2025	Engine	•			
WoF Expiry:	11 Jul 2025	Odometer:	287,640 Kms	Good No:	26526574	Oil level	~			
VIN:	JF1GREKD3BG048200	Next Service:	277,700 Kms	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechar	lical inspection prior to	Coolant condition	~							
	P		S P SC S SC		SC	Performance	~			
Key:		-0	3130 330			Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent R = rust S C SC W						Operation	~			
PT = paint defect						Noise	~			
C = crack						Clutch	~			
P = pin dent						CV joints	~			
						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs P W P S D P W P						Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	r			
body inspection comments						Tyres (lowest observed tread depth of tyres)			es)	
Stone chip in front windscreen						Left front	Left front 3.8			
						Right front	4	.1	mm	
						Left rear	4	.4	mm	
Conditions During Body Inspection: Dry						Right rear	4	.6	mm	
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Stains on f	ront seats, wear	on drivers seat			Head lights	~			
						Tail lights	~			
Carpets	Wear on d	rivers floor mat				Indicators	~			
Panels	Good					Dashboard warning lights	~			
						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
Partial service history						Window winder RR	~			
Two key remotes, one isn't working						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement:YesKms:135,602						Reversing camera			~	
Inspected by: Hoani Saunders Date: 10 Jan 2025										
Inspected by: Hoani Saunders Date: 10 Jan 2025										

I have read and understood this condition guide.

Name:

Signature: