

Report ID: 26,526,751 Version: 1 11 Jan 2025 Created:

Make:	Mini	Model:	Cooper	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2008	<b>Registration:</b>	KKC355	Reg Expiry:	12 Aug 2025	Engine			·	
WoF Expiry:	07 Mar 2025	Odometer:	124,337 Kms	Good No:	26526751	Oil level	~			
VIN:	WMWMF72030TV02454	Next Service:	no sticker	Service Histor	Y: Yes	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise		~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechar	lical inspection prior to	Coolant condition	~							
			SC		S P SC	Performance	~			
Key:		-0			SP SC	Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent R = rust SC D D W						Operation	~			
R = rust PT = paint defect						Noise	~			
C = crack						Clutch			~	
P = pin dent						CV joints	~			
* = decals DPT SC 010 S						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SC W SC W SC W						Performance	~			
Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed trea	Tyres (lowest observed tread depth of tyres)			
						Left front	mm			
						Right front		1 1	mm	
						Left rear	4		mm	
Conditions During Body Inspection: Dry						Right rear		3	mm	
Conditions During Body Inspection: Dry						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
Engine oil l	eak					Steering performance	· ·			
						Shock absorbers	~			
			Air Conditioning / Heater							
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats left seat torn						Head lights	~			
						Tail lights	~			
Carpets	Average					Indicators	· ·			
Panels	Average					Dashboard warning lights	· ·			
	Average					Wipers (front & rear)	~		$\left  - \right $	
Dashboa	rd Average					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	~			
Partial service history						Window winder RR	~			
Rattling noise from engine						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	· ·			
						Number of keys	1		L	
Road Conditions During Test Drive: Dry						Central locking				
Road Conditions During Test Drive: Dry						Remote locking	~		$\left  - \right $	
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)	+		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
	-									
Inspected by: Sione Mae Date: 11 Jan 2025										

I have read and understood this condition guide.

Name: .....

Signature: .....