

Report ID: 26,527,774 1 Version: 11 Jan 2025 Created:

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2013	<b>Registration:</b>	GUJ221	Reg Expiry:	20 Feb 2025	Engine			L	
WoF Expiry:	13 Feb 2025	Odometer:	261,576 Kms	Good No:	26527774	Oil level	~			
VIN:	WBA3D36090NP72989	Next Service:	no sticker	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~			
	[ W		SC SC	S	S	Performance	~			
Key:		=				Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
B = rust	SC W			210	HIL	Operation	~			
PT = paint defe	ect NP				101h	Noise	~			
C = crack					S SC	Clutch			~	
P = pin dent	ssc dle				74116	CV joints	~			
* = decals				Tool .	ELD'S	Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
vv = significant	S W		WW		S P	Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)				
					Left front	4	1	mm		
						Right front	4	1	mm	
						Left rear	4	1	mm	
Conditions During Body Inspection: Dry						Right rear	4 mm			
						Spare	N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Suspected of	oil seepage					Suspension performance	~			
	1 3					Steering performance	۲			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Carpots	A					Tail lights	~			
Carpets	Average					Indicators	~			
Panels	Average					Dashboard warning lights	~			
Dashboa	rd A					Wipers (front & rear)	~			
	rd Average					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
Engine Timing Mechanism: Timing Chain						Remote locking	~			
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~			
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspecter	Inspected by: Sione Mae Date: 11 Jan 2025									
Date: 11 Juli 2023										

I have read and understood this condition guide.

Name: .....

Signature: .....