

Report ID: 26,528,663 1 Version: 13 Jan 2025 Created:

Make:	Holden	Model:	Cruze	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	Registration:	GMW724	Reg Expiry:	18 Sep 2025	Engine			
WoF Expiry:	25 Feb 2025	Odometer:	25,194 Kms	Good No:	26528663	Oil level	~		
VIN:	6G1PE6E80DL800380	Next Service:	39000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	narge.	Coolant condition	~		
	S				S	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = defit R = rust	SC DIA			710	HIVS	Operation	~		T
PT = paint def	ect NP				101h	Noise	~		
C = crack						Clutch			V
P = pin dent	HID				7411L	CV joints	~		
* = decals	- Alt	10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w – signincan	W					Performance	~		
Body Insi	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread	d depth	oftyre	es)
						Left front		5	mm
						Right front		5	mm
						Left rear	4	4	mm
Conditio	ns During Body Ins	pection:				Right rear	4	4	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		1
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		1
		Operation	~						
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		1
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		1
Dashboa	rd Good					Window winder FL	~		1
						Window winder FR	~		1
General Comments						Window winder RL	~		
						Window winder RR	~		1
						Rear view mirrors	~		1
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		1
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	~		1
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspecte	d by: Kilipati Mae					Date: 13 Jan 202	25		

I have read and understood this condition guide.

Name:

Signature: