

Report ID: 26,529,410 6 Version: 13 Jan 2025 Created:

Make:	MG	Model:	ZS	Body Style:	SUV		Pass	Fail	N/A
Year:	2021	Registration:	NQS893	Reg Expiry:	26 Jan 2025	Engine			
WoF Expiry:	24 Jul 2025	Odometer:	24,057 Kms	Good No:	26529410	Oil level			~
VIN:	LSJW74098MZ111228	Next Service:		Service Histor		Smoke & fumes			~
						Performance	~		
	port is not a warranty		с I II	<b>.</b>	1 B 41 1	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	SC	-0	SC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc dl			1n-	EID S	Operation	~		
R = rust				$\prod$	JHIH	Noise	~		
PT = paint defe C = crack				+	SC	Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	PSC PIC			AL.		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs	-	P SC SC			Performance	~		
		Note: som	e defects & blemisbes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•		
Crack in windscreen in sensors area.						Tyres (lowest observed tread depth of tyres)           Left front         5.0 mm			
						Right front	4.		mm
						Left rear		-	
						Right rear	5.	-	mm
Conditions During Body Inspection: Dry							5.5 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare N/A Suspension			
	inage a onder bor	ince inspectie	connents			Suspension performance			
Suspension performance Steering performance							~		
						Shock absorbers	ン ン		
							V		
						Air Conditioning / Heater			
Interior Comments						Operation   Electrical / Accessories			
						Head lights			
Seats	Good						~		
Carpets	Good					Tail lights Indicators	~		
							~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General (	omments					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Full service history with MG is in Leon's office. Towbar tongue in Leon's office.						Window winder RR	~		
Tyre repair kit as opposed to spare wheel.						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
L						Number of keys	2		
Road Conditions During Test Drive:     Dry         Central locking							~		
Engine Timing Mechanism: Unknown Sat Nav (basic test only)							~		
						Sat. Nav. (basic test only)	~		
Lvidence		ement. N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Troy Smith Date: 13 Jan 2025									

Name: .....