

Report ID: 26,531,295 3 Version: 13 Jan 2025 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2010	Registration:	NAU64	Reg Expiry:	24 Feb 2025	Engine				
WoF Expiry:	27 Jan 2026	Odometer:	105,842 Kms	Good No:	26531295	Oil level	~			
VIN:	7AT0C13JX20109916	Next Service:	118000 kms	Service Histor	y: No	Smoke & fumes	~			
Noto: This ro	nort is not a warranty					Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
			ins can be analysed to		lindige.	Coolant condition	~			
Kow	S	5	SC SC			Performance	~			
Key: S = scratch		$\overline{(0)}$		5(O)7		Radiator / Hoses (visual)	~			
						Transmission				
R = rust	SC PP				HILLISS	Operation	~			
PT = paint defe	ect N	1				Noise	~			
C = crack				TTV,		Clutch			~	
P = pin dent * = decals	sc dl				78HB	CV joints	~			
sc = stone chi		10		70		Wheel bearings	~			
W = significant scuffs						Brakes				
		N				Performance	~			
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)				
Roof and Bonnet faded. Minor windscreen chips. Spotlights not working.						Left front	5.	0	mm	
						Right front	5.	0	mm	
						Left rear	4.	0	mm	
Conditions During Body Inspection: Dry						Right rear 4.2 mm			mm	
Under Carriage & Under Bonnet Inspection Comments						Spare N/A				
Under Ca	rriage & Under Bor	net Inspectio	on Comments			Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Commonts						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Carpets	Average					Tail lights	~			
	Average					Indicators	~			
Panels	Average					Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	~			
	rd Average					Window winder FL	~			
Concert						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
In one of the	Inspected by: Chris McQuade Date: 13 Jan 2025									
Inspected by: Chris McQuade Date: 13 Jan 2025										

I have read and understood this condition guide.

Name:

Signature: